


Fence Before 1998



Fence At the time of Tornado in 1998




Tornado Damage in 1998



Tornado Damage in 1998



Existing Fence and Arbor Structure (View from the Sidewalk) – Built After 1998



Existing Fence and Arbor Structure (View from the Street) – Built After 1998



Tree within One Feet of Fence (Inside)



Tree within One Feet of Fence (Outside)